

Field Inspection Report: SPDES GP-0-20-001

Project Name: Pilot Travel Center CTM Proj. #: 21.1029
 Date: August 9, 2021 Time: 4:00 PM Inspector/ Title Ryan Myers, I.E.
 Weather During Inspection 88° Sunny
 Previous 24 hours: Sunny and Dry
 Site Soil Conditions: Saturated soils in low areas
 Description of Run off at Discharge Points None observed

Erosion and Sediment Control Features:		(Refer to Map for Location)
	Condition	Corrective Action Required
Silt Fence	Good	Fix hole in silt fence along western side of site. Add silt fence along downhill side of fenced in laydown area.
Road Sweeping / Offsite	Good	
Construction Entrances	Good	
Riprap Outlet Protection	N/A	
Temporary Sediment Trap(s)	Good	
Erosion Control Blanket	N/A	
Check Dam(s)	N/A	
Concrete Washout	N/A	
Other:	N/A	
Ramp	N/A	

Description of Disturbed Area:	Contractor working on excavating and grading site for parking areas, laydown area, and stockpile areas. Low areas within the disturbed areas contain saturated soils. Silt fence in place around perimeter of disturbed areas. Total disturbed area measured to be +/- 7.1 acres. Contractor obtained 5 acre waiver from DEC.
Description of Stabilized Areas:	Contractor working on grading sand and stone for building foundation pad and the surrounding parking lot areas. Stabilized area of sand and stone measured to be +/- 1.6 acres.


Field Inspection Report: SPDES GP-0-20-001

Areas that Require Stabilization:	None
Permanent Stormwater Management Practices:	

Practices not in conformance with SWPPP: None

Repairs Required: Repair a silt fence section along western side of site that contains a hole.
Add silt fence to downhill side of newly constructed laydown area.

Improvements Since Last Visit: Silt fence at NE and NW corner were fixed and construction entrance was freshened up with new stone to help clean tires of exiting equipment.

Signature of Qualified Inspector: 

Date Inspection Mailed to Owner/Contractor: 8/10/2021

Signature of Owner (if required):