



Ryan,

I drove past the site yesterday and things look generally good. I took the enclosed photo at the easterly side of the site along Riverside Drive. Can you please have the contractor remove some of the silt that has accumulated along the silt fence, so that the capacity is restored for the next rainfall event and the silt fence is not overtopped? It may make sense to have a second row of silt fence farther into the site and parallel with this one as it appears to be the main path of sediment movement on site.

Sincerely,

Douglas P. Cole, PE

Senior Director | Water and Wastewater

KB Group of NY, Inc. dba PRIME AE Group of NY
100 Great Oaks Blvd | Suite 114 | Albany, New York 12203
O: 518 348 7880 | F: 518 382 1776 | dcole@primeeng.com
Connecting. Creating. Conserving. **Community.**
www.primeeng.com

From: Myers, Ryan <r.myers@ctmale.com>

Sent: Tuesday, September 14, 2021 2:47 PM

To: Shane.Warren@pilottravelcenters.com; mary.barrie@dec.ny.gov; Doug Cole

[<dcole@primeeng.com>](mailto:dcole@primeeng.com); glensupervisor@gmail.com; thr56@frontier.com;
sandra.hemstreet@americannational.com

Cc: Edwards, Jim <j.edwards@ctmale.com>; Speulstra, Owen <o.speulstra@ctmale.com>

Subject: Pilot SWPPP Inspection Report 9/14/2021

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Please find the attached SWPPP inspection report for you to review from my site visit on 9/14/2021.

Thank you,

Ryan Myers, I.E.

Civil Engineer I



C.T. Male Associates

A DESIGN PROFESSIONAL CORPORATION

10 North Perry Street, Johnstown, NY 12095

Phone: 518.848.3533

Mobile: 518.706.7290

Email: r.myers@ctmale.com

www.ctmale.com

