## Field Inspection Report: SPDES GP-0-20-001

Project Name:		Pilot Travel Center			CTM P	roj. #:	21.1029
SPDES Permit:		NYR11I522	2				
Date: _	: Oct. 8, 2021		Time:	8:00 AM	Inspector/ Title	Ryan Myer	s, I.E.
Weather During Inspection			60° Ov	ercast			
Previous 24 hours:			Sunny and dry				
Site Soil Conditions:			Soils are slightly saturated in low areas.				
Description of Run off at Discharge Points None observed.							

<b>Erosion and Sediment Control</b>	Features:	(Refer to Map for Location)	
	Condition	Corrective Action Required	
Silt Fence	Good		
Road Sweeping / Offsite	Good		
Construction Entrances	Good		
Riprap Outlet Protection	N/A		
Temporary Sediment Trap(s)	Good		
Erosion Control Blanket	N/A		
Check Dam(s)	N/A		
Concrete Washout	Fair	Create new washout prior to next concrete pour.	
Other: Silt Socks	Good		
Ramp	N/A		
Description of Disturbed Area:	Contractor working on excavating and grading site for proposed driveways, parking areas, utilities, fuel tanks, and stormwater practices. Soils are drying out. Silt fence in place around perimeter of disturbed areas. Total disturbed area measured to be +/- 6.8 acres.		
Description of Stabilized Areas:	Contractor working on grading stone for truck parking areas and driveways. Contractor working on forming and pouring foundations for main building and erecting steel for gas pump canopies. Stabilized area of stone and concrete measured to be +/- 4.7 acres.		

## Field Inspection Report: SPDES GP-0-20-001

Areas that Require Stabilization:	None						
Permanent Stormwater							
Management Practices:							
<u> </u>							
Practices not in conformance with SWPPP: None.							
Repairs Required: Create new concrete washout pit prior to next concrete pour.							
•							
Improvements Since Last Visit: None.							
Signature of Qualified Inspector: Apr H. My							
·	• •						
Date Inspection Mailed to Owner/Contractor: 10/8/2021							
Signature of Owner (if required):							