Field Inspection Report: SPDES GP-0-20-001

Project Name:	Pilot Travel	Center	СТМ	Proj. #:	21.1029	
SPDES Permit: NYR11I522		2				
Date: Oct. 12,	2021	Time: 8:00 AM	_ Inspector/ Title	Ryan Mye	ers, I.E.	
Weather During Inspection		56° Overcast				
Previous 24 hours:		Sunny and dry				
Site Soil Conditions:		Soils are slightly saturated in low areas.				
Description of Run off at Discharge Points None observed.						

Erosion and Sediment Contro	(Refer to Map for Location)			
	Condition	Corrective Action Required		
Silt Fence	Good			
Road Sweeping / Offsite	Good			
Construction Entrances	Good			
Riprap Outlet Protection	N/A			
Temporary Sediment Trap(s)	Good			
Erosion Control Blanket	N/A			
Check Dam(s)	N/A			
Concrete Washout	Fair	Create new washout prior to next concrete pour.		
Other: Silt Socks	Good			
Ramp	N/A			
Description of Disturbed Area:	proposed drive stormwater pr place around	Contractor working on excavating and grading site for proposed driveways, parking areas, utilities, fuel tanks, and stormwater practices. Soils are drying out. Silt fence in place around perimeter of disturbed areas. Total disturbed area measured to be +/- 6.9 acres.		
Description of Stabilized Areas:	Contractor wor areas. Contra- foundations for pump canopies	Contractor working on grading subbase for paved/concrete areas. Contractor working on forming and pouring foundations for main building and erecting steel for gas pump canopies. Stabilized area of stone and concrete measured to be +/- 4.6 acres.		

Field Inspection Report: SPDES GP-0-20-001

Areas that Require Stabilization:	None
Permanent Stormwater	
Management Practices:	

Practices not in conformance with SWPPP: None.

Repairs Required: Create new concrete washout pit prior to next concrete pour.

Improvements Since Last Visit: None.

Signature of Qualified Inspector: Ma R. My

Date Inspection Mailed to Owner/Contractor: 10/12/2021

Signature of Owner (if required):