Field Inspection Report: SPDES GP-0-20-001

Project Name:		Pilot Travel Center			CTM Pi	oj. #:	21.1029
SPDES Permit:		NYR11I522	2				
Date:	Oct. 25,	2021	Time:	4:00 PM	_ Inspector/ Title	Ryan Mye	rs, I.E.
Weather During Inspection			50° Ov	vercast			
Previous 24 hours:			Partly cloudy with some rain				
Site Soil Conditions:			Soils are saturated in low areas with some standing water.				
Description of Run off at Discharge Poin				Points Clean	water discharging	from tem	porary pond.

Erosion and Sediment Control	Features:	(Refer to Map for Location)	
	Condition	Corrective Action Required	
Silt Fence	Good		
Road Sweeping / Offsite	Good		
Construction Entrances	Good		
Riprap Outlet Protection	N/A		
Temporary Sediment Trap(s)	Good		
Erosion Control Blanket	N/A		
Check Dam(s)	N/A		
Concrete Washout	Good		
Other: Silt Socks	Good		
Ramp	N/A		
Inlet Protection	Good		
Description of Disturbed Area:	Contractor working on excavating and grading site for proposed driveways, parking areas, utilities, fuel tanks, and stormwater practices. Soils are saturated from rain with some standing water in low areas. Silt fence in place around perimeter of disturbed areas. Total disturbed area measured to be +/- 5.9 acres.		
Description of Stabilized Areas:	Contractor working on grading subbase for paved/concrete areas. Contractor started working on setting steel for the building. Stabilized area of stone and concrete measured to be +/- 5.6 acres.		

Field Inspection Report: SPDES GP-0-20-001

Areas that Require Stabilization:	None					
Permanent Stormwater						
Management Practices:						
<u> </u>						
Practices not in conformance with SWPPP: None.						
Repairs Required: None.						
- repaire requirement received						
Improvements Since Last Visit: No repairs were needed during last site visit.						
Signature of Qualified Inspector: Apr 1. My						
Oignature of Qualified inspector.						
Date Inspection Mailed to Owner/Contractor: 10/26/2021						
Signature of Owner (if required):						