

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 28, 2021

General Site Photos



Figure 1 - View subbase grading for gas pump area, looking southeast.



Figure 2 - View of subbase grading for eastern driveway, looking north.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 28, 2021



Figure 3 – View of stormwater pond at south end of site, looking southeast.



Figure 4 – View of subbase grading along western side of site, looking north.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 28, 2021



Figure 5 - View of steel erection for building, looking southwest.