

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 2, 2021

Repairs Required



Figure 1 - Refresh the compacted stone for the construction entrance.



Figure 2 - Add inlet protection around low structures.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 2, 2021

General Site Photos



Figure 1 – View of subbase grading for front parking area, looking northwest.



Figure 2 – View of steel erection for building, looking west.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 2, 2021



Figure 3 - View of subbase grading for western side of site, looking north.



Figure 4 - View of subbase grading for truck fuel pump area, looking northeast.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 2, 2021



Figure 5 - View of grading for bioretention area along west side of site, looking northwest.