

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

August 9, 2021

Repairs Required



Figure 1 -Hole in silt fence along western side of site, need to replace section.



Figure 2 - Continue silt fence along downhill side of laydown area.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

August 9, 2021

General Site Photos



Figure 1 – View of construction entrance at north end of site.



Figure 2 – View of front parking area and laydown area, looking southeast.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

August 9, 2021



Figure 3 – View of building foundation pad, looking south.



Figure 4 – Repaired silt fence in NW corner of site.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

August 9, 2021



Figure 5 – Repaired silt fence in NE corner of site.



Figure 6 – View of stockpile area at southern end of site.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

August 9, 2021



Figure 5 – View of proposed gas pump area, looking north.



Figure 6 – View of fenced in laydown area, looking east.