REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center September 28, 2021

Repairs Required



Figure 1 - Clean out silt from along silt fence at north end of site.

C.T. Male Associates Page 1

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center September 28, 2021

General Site Photos



Figure 1 - View of grading and steel erection for truck fuel pump area, looking north.



Figure 2 - View of subbase grading for back truck parking area, looking east.

C.T. Male Associates Page 2

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center September 28, 2021



Figure 3 – View of silt fence along south end of site, looking west.



Figure 4 - View of grading for east bioretention pond at north end of site, looking northwest.

C.T. Male Associates Page 3