

# REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 15, 2021

---

## Repairs Required



Figure 1 - Add inlet protection around low structures.

# REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 15, 2021

---

## General Site Photos



Figure 1 – View of concrete work for building foundation, looking west.



Figure 2 – View of subbase grading for truck fuel pump area, looking southwest.



# REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 15, 2021

---



Figure 3 - View subbase grading for back parking area, looking northwest.



Figure 4 - View of grading for stormwater pond at south end of site, looking east.