

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 19, 2021

Repairs Required



Figure 1 - Refresh the compacted stone for the construction entrance.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 19, 2021

General Site Photos



Figure 1 – View of subbase grading for truck parking area, looking west.



Figure 2 – View of stormwater pond along south end of site, looking south.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 19, 2021



Figure 3 - View of subbase grading for western side of site, looking north.



Figure 4 - View of truck fuel pump area, looking northeast.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 19, 2021



Figure 5 - View of building foundation, looking southeast.