

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 5, 2021

Repairs Required



Figure 1 - Add inlet protection around low structures.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 5, 2021

General Site Photos



Figure 1 – View of grading for south stormwater pond, looking south.



Figure 2 – View of steel erection for building, looking west.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 5, 2021



Figure 3 – View of subbase grading for front parking and fuel pumps, looking west.



Figure 4 – View of subbase grading for western driveway, looking north.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 5, 2021



Figure 5 – View of grading for bioretention area along west side of site, looking northwest.



Figure 6 – View of grading for stormwater pond in NW corner of site, looking west.