

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 10, 2021

Repairs Required



Figure 1 - Add inlet protection around low structures.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 10, 2021

General Site Photos



Figure 1 – View of subbase grading and new curb for western driveway, looking northeast.



Figure 2 – View of steel erection for building, looking northeast.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 10, 2021



Figure 3 – View of subbase grading for front parking and fuel pumps, looking east.



Figure 4 – View of grading and outlet structure for southern stormwater pond, looking southeast.