

# REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 8, 2021

---

## General Site Photos



Figure 1 – View of west driveway entrance, looking east.



Figure 2 – View of grading for west driveway, looking north.

# REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 8, 2021

---



Figure 3 – View of truck fuel pump area subbase grading, looking west.



Figure 4 – View of concrete work for building foundation, looking northeast.

# REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 8, 2021

---



Figure 5 - View of temporary sediment pond in NW corner of site.