

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 12, 2021

General Site Photos



Figure 1 – View of front bioretention area, looking east.



Figure 2 – View of grading for east driveway and stormwater practice, looking south.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 12, 2021



Figure 3 – View of subbase grading for truck parking area, looking west.



Figure 4 – View of truck fuel pump area, looking east.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 12, 2021



Figure 5 - View of concrete work for building foundation, looking east.