

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

October 25, 2021

General Site Photos



Figure 1 – View of temporary sediment pond in northwest corner of site.



Figure 2 – View of new curb along eastern side of site, looking southeast.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 25, 2021



Figure 3 - View of subbase grading and new curb for truck parking area, looking west.



Figure 4 - View of subbase grading along western side of site, looking north.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

October 25, 2021



Figure 5 - View of stormwater pond along south end of site, looking south.