

# REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 19, 2021

---

## General Site Photos



Figure 1 - View of subbase grading and new curb for western driveway, looking northeast.



Figure 2 - View of NW stormwater pond and outlet structure, looking northwest.



# REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 19, 2021

---



Figure 3 – View of steel erection for the main building, looking southeast.



Figure 4 – View of grading and outlet structure for southern stormwater pond, looking southeast.

# REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center  
November 19, 2021

---



Figure 5 – View of paving for back parking area, looking east.



Figure 6 – View of paving work for truck fuel pump area, looking north.



# REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 19, 2021

---



Figure 6 - Low sanitary structure raised and cover installed.