

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 24, 2021

General Site Photos



Figure 1 – View of culvert beneath the eastern driveway, looking southeast.



Figure 2 – View of building and drive thru area, looking southwest.

REPRESENTATIVE PHOTOGRAPHS – SWPPP INSPECTION

Pilot Travel Center

November 24, 2021



Figure 3 – View of gas pump area and front parking lot, looking west.



Figure 4 – View of southern stormwater pond, looking west.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center
November 24, 2021



Figure 5 - Outlet for southern stormwater pond.



Figure 6 - View of western half of front parking lot, looking north.

REPRESENTATIVE PHOTOGRAPHS - SWPPP INSPECTION

Pilot Travel Center

November 24, 2021



Figure 7 - View of western driveway, looking north.